



279326

PAGE _____ OF _____

SAMPLE FIELD SHEET *

DW1

Site Name: 1421 Lamar Ct.
IDEM/OLQ Sample #: E2 NX0
Collection Date: 9 / 12 / 2006

County: Elkhart
Sample ID: E2 NX0
Time: 2:00 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

outside tap, E side of house

For Well Samples: Well purged less than ☒ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purge Time 0 min Purged to dryness? ☐ Yes ☒ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: glass bottles

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Renter: Burt Skinner 574-522-3533 Owner: Neil Thomas 269-6636122

Deviations from Sampling Plan:

574-250-7646 cell phone

SAMPLE FIELD SHEET *

DWZ

Site Name: <u>Elkhart Plating 1413 Fourteenth</u>	County: <u>Elkhart</u>
IDEM/OLQ Sample #: <u>E2NX-1</u>	Sample ID: <u>E2NX1</u>
Collection Date: <u>9/12/06</u>	Time: <u>2:00 AM/PM</u>

Sample Types (check all applicable): ☒ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of ☒ Other Indust. Well

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>20ml</u>	<u>water</u>		<u>HCl</u>	<u>VOC</u>
	<u>20ml</u>	<u>water</u>		<u>HCl</u>	<u>VOC</u>
	<u>20ml</u>	<u>water</u>		<u>HCl</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

90 ft well, DNR well records on file, GPS data available,
well pumping rates available from company & DNR, 10 min. purge

For Well Samples: Well purged less than ☒ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☒ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: glass bottles

Field Test Performed Result

None

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Clear, odorless

Deviations from Sampling Plan: None

SAMPLE FIELD SHEET *

DW 3

Site Name: 1519 Elliston

County: Elkhart

IDEM/OLQ Sample #: E2NX2

Sample ID: E2NX2

Collection Date: 9/12/2006

Time: 4:35 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

South side of house (faces railroad track) by A/C unit

For Well Samples: Well purged less than ☒ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
10 min purge Purged to dryness? ☐ Yes ☒ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: glass bottles

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan:

SAMPLE FIELD SHEET *

DW4

Site Name: 1519 Ellison

County: Elkhart

IDEM/OLQ Sample #: E2NX3

Sample ID: E2NX3

Collection Date: 9 / 12 / 2006

Time: 4 : 31 AM / (PM)

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>
	<u>20 mL</u>	<u>water</u>	<u>20 mL</u>	<u>HCl</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

South side of house (faces railroad track) by A/C unit

For Well Samples: Well purged less than ☒ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
10 min purge Purged to dryness? ☐ Yes ☒ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: glass bottles

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Duplicate of E2NX2

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

PAGE 1 OF 1

DW5

Site Name: Lusher Ave

County: Elkhart

IDEM/OLQ Sample #: DW5

Sample ID: ~~E2N23~~ E2N24

Collection Date: 9/12/06

Time: 5:30 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☒ Duplicate of E2N23 ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

1520 Alhambra

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan:

Water obtained without permission

SAMPLE FIELD SHEET *

DW 6

Site Name: Lusher Ave. Crawfish County: _____

IDEM/OLQ Sample #: _____

Sample ID: E2N40

Collection Date: 9/12/06

Time: 7:30 (AM/PM)

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☒ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>4.0 ml</u>	<u>glass</u>	<u>3</u>	<u>HEL</u>	<u>DOE</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Trip Blank - IDEM - Shadeland Air Lake

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

DW 7

Site Name: Leslie Avenue

County: Elkhart

IDEM/OLQ Sample #: DW 7

Sample ID: EDN 16

Collection Date: 9/12/06

Time: 12:20 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40ml</u>	<u>glass</u>	<u>3</u>	<u>HCL</u>	<u>VOE</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

1306 Raymond
Elkhart 46516 295-4193 4 people

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____

DW8

SAMPLE FIELD SHEET *

Site Name: LUSHER AVE Site
IDEM/OLQ Sample #: DW8
Collection Date: 9/12/06

County: ELKHART
Sample ID: E2NY7
Time: 2:59 AM (PM)

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 ml</u>	<u>Glass</u>	<u>3</u>	<u>HCl</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

James P. Ritchie @ 1308 W. Hubbard 294-3876
2 residents

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Doesn't like taste. Drinks Bottled water.

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

DW9

Site Name: <u>Elbert Lusher Av.</u>	County: <u>Elbert</u>
IDEM/OLQ Sample #: <u>DW9</u>	Sample ID: <u>E2N18</u>
Collection Date: <u>9/12/06</u>	Time: <u>3:25</u> AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40</u>	<u>Plastic</u>	<u>3</u>	<u>HCL</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Oressie Kirk Elbert 46516
1911 S. 13th St. 295-8748
3 People

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

DW10

Site Name: Lusher

County: Elkhart

IDEM/OLQ Sample #: DW10

Sample ID: E2N19

Collection Date: 9/12/06

Time: 3:50 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40</u>	<u>glass</u>	<u>3</u>	<u>HCL</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Edith Fernanglay 296-8040
2033 15th St. Elkhart, IN 46516

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed	Result	Field Test Performed	Result
_____	_____	_____	_____
_____	_____	_____	_____

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

DW11

Site Name: <u>Lusher Ave</u>	County: <u>Elkhart</u>
IDEM/OLQ Sample #: _____	Sample ID: <u>E2N20</u>
Collection Date: <u>9/12/06</u>	Time: <u>4:35 AM</u> (PM)

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 ml</u>	<u>glass</u>	<u>3</u>	<u>HCL</u>	<u>VOC</u>

Sample Location Information (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Margaret Hamm
319 Concord
Elkhart 46516
4 People

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Bad taste & odors

Deviations from Sampling Plan: _____

SAMPLE FIELD SHEET *

Site Name: <u>Lusher Avernue</u>	County: <u>Elkhart</u>
IDEM/OLQ Sample #: <u>DW12</u>	Sample ID: <u>E2N21</u>
Collection Date: <u>9/12/06</u>	Time: <u>4:45</u> AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40</u>	<u>glass</u>	<u>3</u>	<u>HCL</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

505197 County Rd. 15W
Elkhart, IN 46514
1334 Concord
NO Resealed
House is for sale / photo attached

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan:

5 minute purge only - well well
Running after 10 minutes

SAMPLE FIELD SHEET *

DW13

Site Name: <u>Lecher</u>	County: <u>Elkhart</u>
IDEM/OLQ Sample #: <u>DW13</u>	Sample ID: <u>E2N22</u>
Collection Date: <u>9/12/06</u>	Time: <u>5:30</u> AM / PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40</u>	<u>Glass</u>	<u>3</u>	<u>HCL</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

1520 A Lecher

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: NO one home, water altered without permission

SAMPLE FIELD SHEET *

DW14

Site Name: Lusher Ave.

County: Elkhart

IDEM/OLQ Sample #: DW14

Sample ID: E2NZ6

Collection Date: 9/12/06

Time: 12:28 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☒ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40ml</u>	<u>Glass</u>	<u>29</u>	<u>HCl</u>	<u>VOC</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Todd & Pam Suomela 1309 Concord Ave. Elkhart #46516 574-522-4422
Sample taken from outside faucet E/S of house. 4 residents

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

well @ 4 yrs. old (2002) maintains well drilling 862-2318
line, no noticeable color odor problems. well in front of house

Deviations from Sampling Plan: None

SAMPLE FIELD SHEET *

DW15

Site Name: Lusher Avenue
IDEM/OLQ Sample #: DW15
Collection Date: 9/12/06

County: Elkhart
Sample ID: E2N27
Time: 1:15 AM/PM

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40 ml</u>	<u>Glass</u>	<u>3</u>	<u>HCl</u>	

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

1320 Concord Elkhart 46516 Martha Bentley 574-522-
1 resident (corner address 1023 Bentvue Ave. Elkhart 46517 2830)

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

no noticeable smell taste possibly 14' deep

Deviations from Sampling Plan: none

SAMPLE FIELD SHEET *

DW17 DW16

Site Name: <u>Lush</u>	County: <u>Elkhart</u>
IDEM/OLQ Sample #: <u>DW17 DW16</u>	Sample ID: <u>E2120</u>
Collection Date: <u>9/12/06</u>	Time: <u>1:45 AM</u> (PM)

Sample Types (check all applicable): ☐ Mon. Well ☒ Res. Well ☐ Creek ☐ Leachate ☐ Ditch

☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste

☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste

☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank

☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis

Sample Location Information (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Panel 1 293-6975
12/13 concrete Elkhart 465/6

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____

9-12-06

SAMPLE FIELD SHEET *

DW17

Site Name: Leashey Ave.

County: Elkhart

IDEM/OLQ Sample #: DW17

Sample ID: E2N29

Collection Date: 9/12/06

Time: 2:50AM (PM)

Sample Types (check all applicable): ☐ Mon. Well ☐ Res. Well ☐ Creek ☐ Leachate ☐ Ditch
☐ Drainage Tile ☐ Lagoon ☐ Pond ☐ Sludge ☐ Sediment ☐ Industrial Waste
☐ Waste Pile ☐ Soil ☐ Truck ☐ Solvent ☐ Oil ☐ Drummed Waste
☐ Waste Liquid ☐ Sand ☐ Ash ☐ Trip Blank ☐ Field Blank ☐ Equipment Blank
☐ Background ☐ MS/MSD ☐ Duplicate of _____ ☐ Other _____

Containers:	Volume	Material	Quantity	Preservative	Analysis
	<u>40ml</u>	<u>glass</u>	<u>3</u>	<u>HCl</u>	<u>VOE</u>

Sample Location Information: (location marker, depth taken, flow rate, vegetation damage, wildlife present, etc.)

Forest Lewis
1307 Hubbard

574/315-0164
Elkhart 46516

For Well Samples: Well purged less than ☐ 1 ☐ 2 ☐ 4 ☐ 6 ☐ 12 ☐ 24 ☐ 48 hours prior to sampling.
Purged to dryness? ☐ Yes ☐ No Approx. ☐ 1 ☐ 2 ☐ 3 ☐ 5 ☐ >5 well volumes.

Sampling Equipment Used: _____

Field Test Performed Result

Field Test Performed Result

Sample Appearance and Observations: (color, odor, clarity, suspended solids, reaction to preservatives, etc.)

Deviations from Sampling Plan: _____